





# 39351/ZW3010

## Parameter and Command Class List

Parameter number	Parameter:	Length	Valid value	Description
3	LED indication configuration	1	O(default),1,2,3	0 = The device is ON, LED is OFF; the device is OFF, LED is ON 1 = The device is ON, LED is ON; the device is OFF, LED is OFF 2 = LED always OFF 3 = LED always ON
6	Dim up/down rate	1	O(default),I	0 = Dim up/down the light to the specified level quickly by command except value O and FF 1 = Dim up/down the light to the specified level slowly by command except value O and FF
16	Enable/Disable Switch mode	1	O(default),I	0 = Disable 1 = Enable
19	Alternate exclusion	1	O(default),I	0 = Press any button on the switch 1 = Press two times ON button and two times OFF button, LED will flash 5 times if exclusion succeed
30	Minimum Dim Threshold	1	I(default)-99	Set the minimum dimmer threshold when manually or remotely controlled 1=1% 99 = 99%
31	Maximum Brightness Threshold	1	99 (default )-1	Set the maximum brightness threshold when manually remotely controlled 99= 99% 1= 1%
32	Default Brightness Level	1	O(default), 1-99	Set the default brightness level that the dimmer will turn on when being turned on manually 1=1% 99 = 99%

## 39351/ZW3010

### Parameter and Command Class List

---

Z-Wave Plus Role Type: Always On Slave  
Command Class Z-Wave+ Info, Version 2  
Command Class Switch Multilevel, Version 4  
Command Class Association, Version 2  
Command Class Association Group Info, Version 1  
Command Class Manufacturer Specific, Version 2  
Command Class Transport Service, Version 2  
Command Class Device Reset Locally, Version 1  
Command Class Power level, Version 1  
Command Class Central Scene, Version 3  
Command Class Security 2, Version 1  
Command Class Supervision, Version 1  
Command Class Configuration, Version 4  
Command Class Application Status, Version 1  
Command Class Firmware Update Md, Version 4

#### **Button Press Methods**

CycleLED = Press 3 up then 1 down to cycle through LED status  
Switch Mode = Press 5 up then 5 down if done successfully the LED will blink 5 times  
Factory Reset= Press 3 up then 3 down if done successfully the LED will blink 5 times  
Min Threshold = Press 4 down then 1 up, if done successfully the device will turn to 1% and the LED will start to blink signaling the device is in setup mode. Press and hold up or down to adjust the device to the desired minimum threshold.  
Max Threshold = Press 4 up then 1 down, if done successfully the device will turn to 99% and the LED will start to blink signaling the device is in setup mode. Press and hold down or up to adjust the device to the desired maximum threshold.